Oil Field Environmental Incident Summary

Responsible Party: EOG Resources.com **Well Operator:** EOG RESOURCES, INC.

Well Name: BERT 1-28H

Field Name: PARSHALL Well File #: 17189

Date Incident: 1/31/2014 Time Incident: 12:00 Facility ID Number:

County: MOUNTRAIL Twp: 153 Rng: 90 Sec: 28 Qtr: SE SE

Location Description:

Submitted By: Luigi Heydt Received By:

Contact Person: Luigi Heydt

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	barrels	0.5	barrels	0.5	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/5/2014 Clean Up Concluded: 1/31/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

A crew was called to clean up the spill. The affected snow and soil was removed and palced on pit liner to be hauled to disposal. The fluid in the flare pit was removed using a vac truck.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 2/4/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, did not remain on location. Followup is necessary.

Date: 2/11/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 9:45 2/11/14.

Very small amount of material impacted areas off of location. No remediation work was done by EOG. This action is deemed appropriate due to the minimal effect of sprayed material.

No followup necessary.